Savannah River

How do you report Deferred Maintenance for Roads?

Debbie Etheredge Savannah River Site October 21-23, 2008









Agenda

- SRS Pavement Inspection Process
 - What is your site's Pavement Inspection Process?
- SRS Road Network System
 - Does your site have a Road Network System?
- Does Your Site Have Road OSF's in CAIS?
 - If yes, How Does It Compare to other sites?
 - What is your site Road CAS Frequency?
- How do you enter Road OSF's in CAIS Web?
 - What fields do you use?
 - What Crosswalk CAIS Web Fields does your site use?



SRS Pavement Inspection Process

Pavement Inspection Process

- SRS uses Infrastructure 2000 software by Vanasse Hangen Brustlin comprehensive highway maintenance system & tracks pavement condition, highway signage, striping condition, traffic signals & forecast the effect of maintenance expenditures
- Ensure data is analyzed equally & provides a logical basis for maintenance recommendations.

Road Network

- SRS roads are divided into segments based on key intersections.
 - Roads designated by:

```
number - generally run east-west & begin -00 letter - generally run north-sought & begin - 1
```

- 1st 3 digits identify road
- 2nd 3 digits identify segment
 Example 001010 1st segment of Road 1
 102010 1st segment of Road B



SRS CAIS Entry Process

Assessment Frequency

- Asphalt industry recommends Pavement Inspection every 3 yrs.
 - 1/3 Roads inspected every year using SME Road Schedule



SRS OSF Road IU Example

Tracking #:	2103		Insp. ID:	CHARD SWYGERT 💌	Discipline:	CIVIL
Volume:	G20 / Sitework Improvements		WBS: Sit	e;Roads+Walks 💌		
Component:	PAVING;ROADWAYS / SQYD	▼				
Type: ASPHALTIC CONC;WEARING COURSE;2" / 321216130852						
Desc: CRACK SEALING, A AREA EXIT TO RD 2		(Road Segment				
Location:	ROADS	▼	Loc 1:	SEGMENT 104020	Loc 2:	62789
Loc 3:			Loc 4:		Last Yrs. DM (Cost - FY08
Repl. Cst:			Rpr. Cst:	\$1 0,386	Complt. Cst:	
Qty:	30,604		Repl. Qty:		Base Cost:	\$6,615
Official Cst:	\$62,789		Est. Cst:	\$39,993	Next Insp. Date:	06/01/2011
Yr Installed:			Pre Repair Yrs:	2008	Post Rpr Yrs:	
Condition:	FAIR <25% <u>▼</u>		Insp. Date:	06/01/2008	Creation Date:	06/04/2008 02:4
Urgency:	REPAIR IN 1-2 YEARS		Last Remodeled:	07/25/2005	Last Updated:	10/07/2008 03:1
Site Defined:		•	(Last Inspe	ection Date)	2007
Completion Yr	:	Def. Maint.:	Yes ▼ RIC FI	ag: No ▼ RIC Type:		▼
Project ID:	Locked Flag:	Last Updt By:	DETHER	REDGE FY Ba	seline:	08/28/2008
Service:	OPERATING Tracking/Work Order:					
Status:	IDENTIFIED ▼		Repair Symptom:		▼	
Importance:	PRIMARY		Repair Task:			▼
Access:	Repair Cause:		se:	▼		
Equipment ID:			Repair Purpose: EXCEEDED DESIGN		N LIFE ▼	
Comment:	SEGMENT # 104020,A-AREA EXIT TO RD 2,LENGTH - 12520', WIDTH -22', AREA -275440 SQ. FT.,30604 SQ. YD., 2.37 MILE,TRANSVERSE/LONG CRACKING					



Crosswalk: Loc 1: Road segment#, Loc 2: FY08 DM cost, Last

Remodeled: Last Inspection Date

Road OSF's in CAIS?

- Does Your Site Have Road OSF's in CAIS?
 - What is your site Road CAS Frequency?
 - Do you have a Road Network Identification system?
 - Use any Road Crosswalk Terminology?

SRS Terms CAIS Deficiency Terms

Alligator Cracking Longitudinal or Transverse Cracks

Block Cracking " "

Longitudinal or Trans

Corrugations HeavingDistortion Rutting

Raveling Surface Raveling

Pot Hole & Non-Util.
 Potholes

If Yes, How does it compare to other sites?



Questions / Discussion

Debbie Etheredge
 Savannah River Site
 Aiken, South Carolina
 803-952-9752
 debbie.etheredge@srs.gov

